



Codes & Standards


DIN 4109

ISO 3822

Ü-Zeichen

Certificates and sustainability

LGA_38



Spare parts list

No.	Item Number	Name	Quantity used	Delivery time
6	09 21 02 151 90	sleeve	1.00	2
1	09 20 98 001-33	handle	1.00	60
2	09 12 12 005 90	fixing cap	1.00	2
7	90 90 03 202 00 90	top	1.00	2
8	09 31 11 004 90	pin	1.00	60
5	90 27 67 021 94-33	rosette	1.00	30
4	09 14 10 017 90	seal	1.00	2
3	09 12 12 043-33	base	1.00	60